



Figure 1

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Rotorcraft Standards Staff, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Rotorcraft Standards Staff.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Rotorcraft Standards Staff.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(e) This amendment becomes effective on April 7, 1999.

**Note 3:** The subject of this AD is addressed in Direction Generale De L'Aviation Civile (France) AD 96-081-036(B)R1, and AD 96-082-054(B)R1, both dated April 24, 1996.

Issued in Fort Worth, Texas, on February 24, 1999.

**Henry A. Armstrong,**

*Manager, Rotorcraft Directorate, Aircraft Certification Service.*

[FR Doc. 99-5178 Filed 3-2-99; 8:45 am]

BILLING CODE 4910-13-U

## DEPARTMENT OF THE TREASURY

### Internal Revenue Service

#### 26 CFR Parts 1 and 602

[TD 8795]

RIN 1545-AT78

#### Notice of Significant Reduction in the Rate of Future Benefit Accrual; Correction

**AGENCY:** Internal Revenue Service (IRS), Treasury.

**ACTION:** Correction to final regulations.

**SUMMARY:** This document contains corrections to Treasury Decision 8795, which was published in the **Federal Register** on Monday, December 14, 1998 (63 FR 68678) relating to defined benefit plans and to individual account plans that are subject to the funding standards of section 302 of the Employment Retirement Income Security Act of 1974.

**DATES:** These corrections are effective December 14, 1998.

**FOR FURTHER INFORMATION CONTACT:** Diane S. Bloom, (202) 622-6214 or Christine L. Keller, (202) 622-6090 (not toll-free numbers).

#### SUPPLEMENTARY INFORMATION:

##### Background

The final regulations that are the subject of these corrections are under

section 411 of the Internal Revenue Code.

#### Need for Correction

As published, TD 8795 contains errors which may prove to be misleading and are in need of clarification.

#### Correction of Publication

Accordingly, the publication of the final regulations (TD 8795), which was the subject of FR Doc. 98-32925, is corrected as follows:

1. On page 68680, column 2, in the preamble under the paragraph heading "Special Analyses", line 12, the language "24, 1996, the Regulatory Flexibility Act" is corrected to read "29, 1996, the Regulatory Flexibility Act".

#### § 602.101 [Corrected]

2. On page 68684, column 1, § 602.101(c), in the table under the column heading Current OMB control No., the OMB number "1545-1447" is corrected to read "1545-1477".

**Cynthia E. Grigsby,**

*Chief, Regulations Unit, Assistant Chief Counsel (Corporate).*

[FR Doc. 99-5129 Filed 3-2-99; 8:45 am]

BILLING CODE 4830-01-U